

Aero Commander Shrike 500S	
PREPARATION	CRUISE
Essence et inspection	Cowl flaps = CLOSE <input type="button" value="o"/>
Battery = ON	Cruise Power
Beacon = ON	Mixture = BEST POWER
ENG HYD FUEL = ON	DEICE
	DEICE ENG = ON
	Pitot Heat = ON
START RIGHT (repeat for LEFT)	
Mixture = CUTOFF	APPROACH
Fuel Pump = ON	Downwing = 110 Kts
MAGNETO = START	Gear and Flaps
Mixture = OPEN	Fuel Pumps = ON
Fuel Pumps = OFF	Base = 85 Kts
Gen/Alternator = ON	Final = 80 Kts
Avionic = ON	
	AFTER LANDING
TAXI	Flaps UP
Trim for Takeoff = 9°	Fuel Pumps = OFF
RUNUP : 1500 RPM	Landing Gear = LOCK
TAKEOFF	SHUTDOWN
Fuel Pumps = ON	Mixture = CUTOFF
Rotate = ~90 kts	Magneto = OFF
Climb = ~96 Kts - 2450 RPM	Avionics = OFF
Gear and Flaps	Lights = OFF
Cowl flaps = verify ENG TEMP <input type="button" value="o"/>	Gen/Alternator = OFF
Fuel Pumps = OFF	Battery = OFF
	FUEL VALVE = CLOSE
	ENG HYD FUEL = OFF